

CTXCR35/CTXCR40 SPROCKET INSTRUCTION

REVISED 4/17/2023

POLARIS CTXCR35 AND CTXCR40 IMPORTANT NOTICE:

ROTATE TRACK UNTIL DRIVE CHAIN IS AT ITS TIGHTEST POINT, AND THEN SET SPROCKET TENSIONER SO THAT CHAIN HAS A ¼ INCH SLACK AT THE TOP OF CHAIN.

NOTE: TO ENSURE PROPER SPROCKET ALIGNMENT, USE A STRAIGHT EDGE BETWEEN DRIVE CLUTCH SPROCKET AND REAR SPROCKET TO SEE IF IDLER IS IN LINE.

RED DOT ON SPROCKET FACES TUNNEL

TECH LINE (319) 462-6932 MONDAY TO FRIDAY 8 AM TO 5PM CST.

*****PLEASE NOTE*****

This product is intended for closed-course racing only and is sold “as-is” without warranty. Manufacturer and distributor specifically disclaim all responsibility for consequential and incidental damages or any other losses arising from the use of this product. Any dispute arising out of the use of this product must be settled in Linn County, Iowa under Iowa law.

CTXCR35/CTXCR40 SPROCKET INSTRUCTION

REVISED 4/17/2023

POLARIS CTXCR35 AND CTXCR40 IMPORTANT NOTICE:

ROTATE TRACK UNTIL DRIVE CHAIN IS AT ITS TIGHTEST POINT, AND THEN SET SPROCKET TENSIONER SO THAT CHAIN HAS A ¼ INCH SLACK AT THE TOP OF CHAIN.

NOTE: TO ENSURE PROPER SPROCKET ALIGNMENT, USE A STRAIGHT EDGE BETWEEN DRIVE CLUTCH SPROCKET AND REAR SPROCKET TO SEE IF IDLER IS IN LINE.

RED DOT ON SPROCKET FACES TUNNEL

TECH LINE (319) 462-6932 MONDAY TO FRIDAY 8 AM TO 5PM CST.

*****PLEASE NOTE*****

This product is intended for closed-course racing only and is sold “as-is” without warranty. Manufacturer and distributor specifically disclaim all responsibility for consequential and incidental damages or any other losses arising from the use of this product. Any dispute arising out of the use of this product must be settled in Linn County, Iowa under Iowa law.
